

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

HY1144
NNE
> 1
1.503 mi.
7934 ft.

MANHOLE 34470
EAST 5TH ST & AVE T
BROOKLYN, NY

NY Spills S107407624
N/A

Site 2 of 2 in cluster HY

Relative:
Higher

Actual:
16 ft.

SPILLS:

Name: MANHOLE 34470
Address: EAST 5TH ST & AVE T
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0005698 / 2003-06-02
Facility ID: 0005698
Facility Type: ER
DER Facility ID: 199684
Site ID: 243083
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4

SWIS: 2401
Spill Date: 2000-08-11
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2000-08-11
CID: 205
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-08-11
Spill Record Last Update: 2003-06-02
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 001
Contact Name: CALLER
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis 132842 B. LEWIS #07854 MECH A CABLE DEPT REPORTS IN MH34470 N.INT. E.5 .ST & AVE T HE FOUND APPROX 1 PINT UNKNOWN OIL ON 200 GALLONS WATER. HE FOUND UNKNOWN OIL WHILE GETTING READY TO PULL SECONDARY CABLE. HE DOES NOT SEE A JOINT REGULATOR OR SUMP OR SEWER CONNECTION AT THIS TIME. LIQUID SEEMS CONTAINED AT THIS TIME, NO SEWERS OR WATERWAYS AFFECTED. CABLE IS THE ONLY OIL FILLED EQUIPMENT IN HOLE. HE TOOK A LIQUID SAMPLE AND REQUESTED A 4-6 HRS PRIORITY FOR SAMPLE RESULTS. CLEANUP PENDING SAMPLE RESULTS. HE PLACED E.S.TAG #11256. NO PARKING RESTRICTIONS CIG W. MURPHY NOTIFIED 1326 HRS LAZ # 04425 UPDATE @ 2330 HRS 8/14 LIPORI REPORTS CLEANUP COMPLETED NO SUMP FOUND & STOP TAG REMOVED. #12255 VDC. Cleanup completed by double washing structure with slix. Liquid waste removed by tanker. Solid waste removed by vacuor. No leaking equip. Incident is closed. TJ - 50495 UPDATE ... 1/27/03 INCIDENT NEVER STATED THE OIL CAME FROM THE SECONDARY CABLE... INCIDENT WAS A SPILL UNKNOWN"
"CALLER REPORTS 1 PT ON 200 GALLONS. SAMPLES. CON ED # 132842."

Remarks:
All Materials:
Site ID:

243083

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Operable Unit ID: 828393
Operable Unit: 01
Material ID: 546847
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported